



BASIS DC PCS - Lead in Water Test Results



FY18 Filter Test - Plumbing Check Retest

Less than 5 ppb - Devices Requiring No Remediation											
Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Filter Test ID	FT Final Results - Draw A (ppb)	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right					
BASIS DC PCS	WS-014-001	Food Prep Sink	1	In kitchen	-	Mid	WF-102017-014001-01	3/16/18	FT-FY18-102017-014001	1.8	<1



Basis DC - Lead in Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation											
Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Filter Test ID	FT Final Results - Draw A (ppb)	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right					
BASIS DC PCS	WS-014-002	Cooler	1	In hallway adjacent to kitchen	Low	Right	WF-102017-014002-01	4/4/2018	FT-FY18-102017-014002	<1	<1
BASIS DC PCS	WS-014-003	Cooler	1	In hallway adjacent to kitchen	High	Left	WF-102017-014003-01	4/4/2018	FT-FY18-102017-014003	<1	<1
BASIS DC PCS	WS-014-004	Cooler	1	In multi purpose room	Low	Right	WF-102017-014004-01	4/4/2018	FT-FY18-102017-014004	<1	<1
BASIS DC PCS	WS-014-005	Cooler	1	In multi purpose room	High	Left	WF-102017-014005-01	4/4/2018	FT-FY18-102017-014005	<1	<1
BASIS DC PCS	WS-014-006	Cooler	2	In hallway adjacent to boys' and girls' restroom	Low	Right	WF-102017-014006-01	4/4/2018	FT-FY18-102017-014006	<1	<1
BASIS DC PCS	WS-014-007	Cooler	2	In hallway adjacent to boys' and girls' restroom	High	Left	WF-102017-014007-01	4/4/2018	FT-FY18-102017-014007	<1	<1
BASIS DC PCS	WS-014-008	Break Room	3	In teachers' lounge room 301			WF-102017-014008-01	4/4/2018	FT-FY18-102017-014008	<1	<1
BASIS DC PCS	WS-014-009	Cooler	3	In hallway adjacent to boys' and girls' restroom	High	Left	WF-102017-014009-01	4/4/2018	FT-FY18-102017-014009	<1	<1
BASIS DC PCS	WS-014-010	Cooler	3	In hallway adjacent to boys' and girls' restroom	Low	Right	WF-102017-014010-01	4/4/2018	FT-FY18-102017-014010	<1	<1
BASIS DC PCS	WS-014-011	Cooler	4	In hallway adjacent to boys' and girls' restroom	High	Left	WF-102017-014011-01	4/4/2018	FT-FY18-102017-014011	<1	<1
BASIS DC PCS	WS-014-012	Cooler	4	In hallway adjacent to boys' and girls' restroom	Low	Right	WF-102017-014012-01	4/4/2018	FT-FY18-102017-014012	<1	<1
BASIS DC PCS	WS-014-013	Break Room	5	In teachers' lounge room 501			WF-102017-014013-01	4/4/2018	FT-FY18-102017-014013	<1	<1
BASIS DC PCS	WS-014-014	Cooler	5	In hallway adjacent to boys' and girls' restroom	High	Left	WF-102017-014014-01	4/4/2018	FT-FY18-102017-014014	<1	<1
BASIS DC PCS	WS-014-015	Cooler	5	In hallway adjacent to boys' and girls' restroom	Low	Right	WF-102017-014015-01	4/4/2018	FT-FY18-102017-014015	<1	<1
BASIS DC PCS	WS-014-016	Cooler	6	In hallway adjacent to room 609	High	Left	WF-102017-014016-01	4/4/2018	FT-FY18-102017-014016	<1	<1
BASIS DC PCS	WS-014-017	Cooler	6	In hallway adjacent to room 609	Low	Right	WF-102017-014017-01	4/4/2018	FT-FY18-102017-014017	<1	<1

Greater than 5 ppb - Devices Requiring Remediation											
Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Filter Test ID	FT Final Results - Draw A (ppb)	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right					
BASIS DC PCS	WS-014-001	Food Prep Sink	1	In kitchen		Mid	WF-102017-014001-01	4/4/2018	FT-FY18-102017-014001	6.1	<1